







SS1



SureSHOT



A mm Ø	B inches Ø	C mm ²		
14.2	5/8"	16	4	SS1-14216
14.2	5/8"	25	4	SS1-14225
14.2	5/8"	35	4	SS1-14235
14.2	5/8"	50	4	SS1-14250
14.2	5/8"	70	4	SS1-14270
14.2	5/8"	95	4	SS1-14295
17.2	3/4"	16	4	SS1-17216
17.2	3/4"	25	4	SS1-17225
17.2	3/4"	35	4	SS1-17235
17.2	3/4"	50	4	SS1-17250
17.2	3/4"	70	4	SS1-17270
17.2	3/4"	95	4	SS1-17295

SS2



A mm Ø	B inches Ø	C mm ²		
14.2	5/8"	16	4	SS2-14216
14.2	5/8"	25	4	SS2-14225
14.2	5/8"	35	4	SS2-14235
14.2	5/8"	50	4	SS2-14250
14.2	5/8"	70	4	SS2-14270
14.2	5/8"	95	4	SS2-14295
17.2	3/4"	16	4	SS2-17216
17.2	3/4"	25	4	SS2-17225
17.2	3/4"	35	4	SS2-17235
17.2	3/4"	50	4	SS2-17250
17.2	3/4"	70	4	SS2-17270
17.2	3/4"	95	4	SS2-17295

Suitable for connections to copperbond rods - for connections to solid copper and stainless steel rods please contact our sales office.

Threaded portion of copperbond rods must be removed prior to welding.